

FIG.1




FIG. 2




FIG. 4

File

Edit

View

Go

Bookmarks

Options

Directory

Window

Help

↩

⏮

⏭

⏪

⏩

🏠

⬆

⬇

⬅

➡

⬆

⬇

⬅

➡

🖨

🔍

📁

http://www.

ENTER COA DATA FOR THE RAW MATERIAL

LOT NUMBER

1001

210

MELT TEMP

300 C

210

HARDNESS

65

210

COLOR

RED

210

SUBMIT

212

Document

Done